

Item 20 = Asbestos Bitumen Coating to Metal Corrugated Roof Sheets to Open Area 1.13

Item 1 = Vermiculite Insulation below Low Level Timber Boxing

Item 3 = Artex Finish to Plasterboard Fixed Ceiling






Item 1 = Vermiculite Insulation below Low Level Timber Boxing

Item 23 = Asphalt Floor Covering to Solid Floor Slab & Section of Wall below Lift Shaft

● = Item 19 = Asbestos Textile Flashguards within Old Electrical Boxes

Item 4 = Asbestos Vinyl Floor Tiles below Radiator within Timber Boxing

Item 5 = Asbestos Millboard Lining between Metal to Iron on the Window

-  = ACMs Removed
-  = ACMs Present
-  = No ACMs Present
-  = No Access Areas
-  = Not in Scope of Inspection

